



800 Commercentre Drive  
Lake Forest, CA 92630  
USA

Telephone: (949) 448-4100  
www.intertek.com

November 15, 2018

Todd Randinelli  
KiwiBond International  
25831 Paradise Road  
Bonita Springs, Florida 34135 USA

**RE: WoolGuard Hood Filters/Naturalsorb wool fiber grease filters for Exhaust Ducts, Model: NaturalPanel WF**

Dear Mr. Randinelli:

This is to confirm that Intertek Testing Services NA, Inc. has tested the above-named products and certifies them for compliance with UL 1046, *Standard for Grease Filters for Exhaust Ducts*. The listing can be verified on the Intertek [Directory of Building Products](#) (search for “Kiwibond”).

Section 507.2.8 of the 2015 International Mechanical Code states that Type I hoods shall be equipped with grease filters listed and labelled in accordance with UL 1046. Naturalsorb grease filters, Model NaturalPanel WF, that are labelled with the ETL Listed Mark comply with UL 1046 and, therefore, comply with IMC Section 507.2.8, provided they are installed in accordance with the installation requirements of the code.

If you have any questions, please do not hesitate to contact us.

Respectfully,

**INTERTEK TESTING SERVICES NA INC.**

Michael Beaton, P.E.  
Vice President, Certification Services



All services undertaken are subject to the following general policy: This report is for the exclusive use of Intertek Testing Services NA Ltd.'s (Intertek's) client and is provided pursuant to the agreement between Intertek and its client. Intertek's responsibility and liability are limited to the terms and conditions of the agreement. Intertek assumes no liability to any party, other than to the client in accordance with the agreement, for any loss, expense or damage occasioned by the use of this report. Only the client is authorized to copy or distribute this report and then only in its entirety. Intertek must first approve any use of the Intertek name or one of its marks for the sale or advertisement of the testing materials, product or service in writing. The observations and test results in the report are relevant only to the sample tested. This report by itself does not imply that the material, product or service is or has ever been under Intertek's certification program.